Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/18018UE-1843/1

Work Order Type: Weatherization Audit Name: 18018UE-1843

CLIENT INFORMATION

Client Name: Address:

Client ID: 18018UE-1843

Alt. Client ID: Hawkins

AGENCY INFORMATION

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Agency Contact: Hoard, Howard Work Phone: (423) 246-6180

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

House has been coverted from old store has size of 36 x 45= 1620 sq. ft.

House has no basement has rockwool in attic and need to build access since curent has hole has window that are size of door need caulk (4)

Door is bad has missing part of glass panel back door 40" x 80" need to be W/s client has long floresant lights with the ballast bad. has replaced some with round florestant lighting. Has air duct in ceiling and has some holes in around lighting. Water heater in client room and has stuff on top.

Client Name:
Client ID: 18018UE-1843
Alt. Client ID: Hawkins

Work Order (Bid Form)
Work Order Name: WO/18018UE-1843/1

DOE Weatherization Assistant Version 8.6.0 Page 1 of 5

Measures

	<i>Measure</i> 1 Do	or Replacement 36" x 80'	1		Componen	ts			Inspected
C		ce main door with half moor g pieces and some framing sed.							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor	Install door	Each	1					
1	Unspecified	Misc Material	Each	1					
C	Other Detail						,		
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

	Measure 2 Seal	Ducts			Componer	its		1	nspected
C	Comment Seal duc	ts and w/s doors							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Duct Sealing	Each	8					
1	Labor	Seal ducts in the sealing area of home	Each	8					
2	Miscellaneous Su	W/S back door 40" x 80"	Each	1					
2	Labor	install w/s back door (door metal)	Each	1					
3	Labor	install W/S front rt door	Each	1					
3	Miscellaneous Su	W/S door front rt of home	Each	1					
4	Labor	Check ductlines for leaks	Each	1					
4	Miscellaneous Su	Check duct work for holes	Each	1					
(Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

1	Measure 3 DW	H Tank Insulation			Componen	ts			Inspected
C	omment Install to	spec TWFG on page 34	4-35						
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equip	DHW Tank Insulation	Each	1					
1	Labor	DHW Tank Insulation	Each	1					
O	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
		H Pipe Insulation o specification of TWFG (on page 3		Componen	ts			Inspected
		-	on page 3		Componen Estimated			Actual	Inspected
C		-	on page 3		•		Qty		Inspected Total
<i>C</i> #	omment Install to	specification of TWFG	. •	7	Estimated		Qty	Actual	
C # 1	omment Install to	Description / Comment	Units	Qty	Estimated		Qty	Actual	
C # 1	omment Install to Material / Labor Insulation	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty	Estimated		Qty	Actual	
C # 1	omment Install to Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty	Estimated		Qty	Actual	
C # 1	omment Install to Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	<i>Units</i> Each	Qty	Estimated		Qty	Actual	
C # 1	omment Install to Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated			Actual	
C # 1	omment Install to Material / Labor Insulation Labor	Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
C # 1	omment Install to Material / Labor Insulation Labor Other Detail	Description / Comment DHW Pipe Insulation	Units Each Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 5 Atti	c Ins. R-38			Componen	ts A1		,	nspecte
Comment Area 16	620 sq. ft. and build acess	s pane to	TWFG	on page 116 Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
¹ Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1620					
l Labor	Attic Insulation - Blown Cellulose - R-38	SqFt	1620					
2 Labor	install access panel	Each	1					
² Miscellaneous Su	Build attic access panel	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work O	rder Gra	nd Total:		Gran	d Total:	